



**DIVERSIFIED**  
**TESTING LABORATORIES, INC.**  
WORLDWIDE SERVICE

“We Test Per Your Request”

336 WEST FRONT STREET  
P.O. BOX 4004  
BURLINGTON, NORTH CAROLINA 27215  
PHONE (336) 227-7710 • FAX (336) 227-1175  
[www.diversifiedtestinglabs.com](http://www.diversifiedtestinglabs.com)

July 17, 2017

MARLEN TEXTILES  
500 Orchard Street  
New Haven, MO 63068

Reference: Laboratory Test Report  
Lab Identification No. 26046  
Invoice No. 57205

Dear Sir or Madam:

One (1) fabric sample, identified as **ODYSSEY OPEN**, was received and tested in accordance with the Motor Vehicle Safety Standard No. 302. The results are as follows:

### TEST RESULTS

The sample submitted stopped burning before it had burned for 60 seconds from the start of timing, and had not burned more than two (2) inches from the point where timing was started.

The sample submitted **meets** the minimum requirements of the above standard. Material cannot burn at a rate of more than 4.00 inches/minute.

If there are any questions or when we can be of further assistance, please let us know.

Sincerely,

Brian S. Dement

BSD/mr

